

WATER MAIN BREAK UPDATE 3: As of 5:00 PM. The leak has been isolated. As you can see in the picture -maybe- it is a crack that goes completely around the pipe. This is actually a good thing because it is easier to install a permanent clamp..

We estimate turning the water back on at roughly 6:00 PM.

Just like the last time, let's hope that the repair holds as they turn the water on slowly.

